

# Wiring Diagram for Stratocaster 5-way Wiring Harness

When you receive your harness, you will notice that I have left the Jack still soldered to the white and black wire. You will have to un-solder it before you install the harness. I hook up the jack whilst building it, so as I can test the harness by hooking it up to a test guitar on my bench. I leave it soldered up, so you can see which wire goes to which lug. You wouldn't believe how many buyers wire it up the wrong way around.

**I also include two ground wires running from the volume pot. One to the tremolo claw which is shown in blue on the wiring diagram and the shorter one shown in black is to hook up the 3 ground wires from the pickups.**

**This eliminates the possibility of you overheating the volume pot. There is no longer a need to solder the 3 pickup ground wires to the back of the volume pot.**

**Scroll down for wiring diagram**

